

**INSPECTION REPORT ROUTINE
 INSPECTION**
**DEP USE
 ONLY**

 Complaint Record
 No.

 Inspection Record
 No.
 4242118

 Enforcement
 Record No.

DEP Office	Cambria Oil & Gas Office		Telephone No.: (814) 472-1900	Permit or Reg. No.:	129-28936
Address	286 Industrial Park Road		Fax No.: ----	Project No.: ----	WellPad: AIKENS 5
	Ebensburg, PA 15931			Farm Name and Well No.:	AIKENS 5 AIKENS5MHSUT
Operator Name	CNX GAS CO LLC			County	Westmoreland
Address	ATTN: ENVIRONMENTAL 1000 CONSOL ENERGY DRIVE CANONSBURG, PA 15317			Municipality	Washington Township
	----			Latitude (DD)	40.504096
OGO No.	OGO-37312	Client ID No.	159257	Longitude (DD)	-79.561058
Drilling Rig / Type	----				
Facility Type	----		Producing Formation	----	

Other	☐ Permit Expired	☐ Alt / Meth	☐ Annulus Open	☐ Conductor Only	Spud Date: 2017- 03-05	☒ Coal	☐ Non- Coal
-------	--	--	--	--	---------------------------	--	---------------------------------------

Remarks / Violations

Category	Sub-Category	Inspection Remarks / Violations / Violation Remarks	I	R	V
Location					
Well					
Waste Management					
Other					

WELL INFORMATION

Well Status: * Active	Well Production Status: Temp. Shut In	Well Type: * Gas	Depth: ft.
Flowback: ☐ Yes ☒ No	Stressed Vegetation: ☐ Yes ☒ No	Wells on Location: 10	
Separators: ☒ Yes ☐ No	Oil Staining: ☐ Yes ☒ No		

**INSPECTION REPORT ROUTINE
 INSPECTION**

Casing	Size			Press (psi)	Volumn (cu ft/d)	Length (ft)	SIPT
1	---- X ----			----	----	----	☐
	0 Hrs: ----	12 Hrs: ----	24 Hrs: ----	48 Hrs: - ----	72 Hrs: ----	Days: ----, - ----	
	Casing: ----			Volumn: ----			
	Gas Detected: ----	Gas Concentation: ----% LEL, ---- % GAS		Method Used: ----		Date Calibrated: ----	
	Additional Comments: ----						

Cellar Observation

Water	☒ Yes ☐ No	Below Grade:	Combustible Gas Detected ☐ Yes ☒ No ☐ Unable to check for gas	
Gravel	☐ Yes ☐ No	Below Grade:	Gas Concentration: % LEL, % GAS	
			Method Used: *	See Date Calibrated:
Bubbling	☐ Yes ☒ No	Rate:	Remarks	

EQUIPMENT ON LOCATION

Equipment on Location		Tanks: [3]	
Dryers: 10	Drips: 0	Brine/Oil: 0	Fresh Water: 0
Pumpjacks: 0	Meters: 10	Flowback: 0	Consolidation: 0
Separators: 10	Containment:	Propane: 0	Poly Vent: 0
Compressors: 0		Production: 3	

RTN Other Data

H2S Detected	☐ Yes ☒ No ppm	Corrosion: Light	Leaking: No
--------------	---	------------------	-------------

**INSPECTION REPORT ROUTINE
 INSPECTION**

Photos Attached	Additional Documents	WQS follow up	Inspection Results
☒ Yes ☐ No	☐ Yes ☒ No	☐ Yes ☐ No	NOVIO - No Violations Noted
Remarks: On 7/22/26 at 9:40 AM, I arrived at the Aikens 5MHSUT well pad to conduct a Routine/Complete inspection on (129-28638). At the time of the inspection the well is open and in production. The well is shut in and currently not in production. The most recent production report for 12/31/25. No production has been submitted for 2026. The annual production report list the well as temporarily not producing. The Mechanical Integrity Assessment list an inspection date of 12/31/25. The report was submitted on 2/13/26. In the report the operator list a Primary Production Pressure of 3263 psig and a Production Annulus Open flow or Shut in Pressure of 597 no corrosion issues. The site has a total of 10 wells, 2 Marcellus and 8 Utica. All the active wells are connected t GPUs and production tanks. At this time no violations will be cited.			
On Site Representative		DEP Representative	
 (signature)		 (signature)	
(print name)		MATTHEW THOMAS WOODS, OIL GAS INSP (print name)	
Date: 07/22/2026	Time Arrived: 09:43 AM	Time Departed: 10:40 AM	

INSPECTION IMAGES



#: 1

Well tree and well number.



#: 2

Marcellus wells GPUs.



#: 3

Production tanks inside impoundments.



#: 4

Both Marcellus wells

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL
PROTECTION OFFICE OF OIL AND GAS
**INSPECTION REPORT ROUTINE
INSPECTION**

**DEP USE
ONLY**

Complaint Record
No.


Inspection Record
No.
4242118

Enforcement
Record No.



#: 5

Well posting at the front of location.



#: 6

PPC plan in case.

v2025.4.2


COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL
PROTECTION OFFICE OF OIL AND GAS
**INSPECTION REPORT ROUTINE
INSPECTION**

**DEP USE
ONLY**

Complaint Record
No.


Inspection Record
No.
4242118

Enforcement
Record No.



#: 7

Emergency response plan in case near posting.



#: 8

Reverse side of ERP.