



v2025.4.2

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL
PROTECTION OFFICE OF OIL AND GAS

**INSPECTION REPORT ROUTINE
INSPECTION**

**DEP USE
ONLY**

Complaint Record
No.

Inspection Record
No.
4249598

Enforcement
Record No.

DEP Office	Cambria Oil & Gas Office		Telephone No.: (814) 472-1900	Permit or Reg. No.:	129-28877
Address	286 Industrial Park Road		Fax No.: ----	Project No.: ----	WellPad: GAUT 4
	Ebensburg, PA 15931		Farm Name and Well No.:		GAUT 4IHSU
Operator Name	CNX GAS CO LLC			County	Westmoreland
Address	ATTN: ENVIRONMENTAL 1000 CONSOL ENERGY DRIVE CANONSBURG, PA 15317			Municipality	Washington Township
	----			Latitude (DD)	40.508223
OGO No.	OGO-37312	Client ID No.	159257	Longitude (DD)	-79.558339
Drilling Rig / Type	----				
Facility Type	----		Producing Formation	----	

Other	☐ Permit Expired	☐ Alt / Meth	☐ Annulus Open	☐ Conductor Only	Spud Date: 2014- 12-12	☒ Coal	☐ Non- Coal
-------	--	--	--	--	---------------------------	--	---------------------------------------

Remarks / Violations						
Category	Sub-Category	Inspection Remarks / Violations / Violation Remarks	I	R	V	
Location						
Well						
Waste Management						
Other						

WELL INFORMATION			
Well Status: * Active	Well Production Status: Shut In	Well Type: * Gas	Depth: ft.
Flowback: ☐ Yes ☒ No	Stressed Vegetation: ☐ Yes ☐ No	Wells on Location: 8	
Separators: ☒ Yes ☐ No	Oil Staining: ☐ Yes ☐ No		

**INSPECTION REPORT ROUTINE
 INSPECTION**

Casing	Size			Press (psi)	Volumn (cu ft/d)	Length (ft)	SIPT
1	---- X ----			----	----	----	☐
	0 Hrs: ----	12 Hrs: ----	24 Hrs: ----	48 Hrs: - ----	72 Hrs: ----	Days: ----, - ----	
	Casing: ----			Volumn: ----			
	Gas Detected: ----	Gas Concentation: ----% LEL, ---- % GAS		Method Used: ----		Date Calibrated: ----	
	Additional Comments: ----						

Cellar Observation

Water	☐ Yes ☐ No	Below Grade:	Combustible Gas Detected ☒ Yes ☐ No ☐ Unable to check for gas	
Gravel	☐ Yes ☐ No	Below Grade:	Gas Concentration: % LEL, % GAS	
			Method Used:	Date Calibrated:
Bubbling	☐ Yes ☐ No	Rate:		

EQUIPMENT ON LOCATION

Equipment on Location		Tanks: [2]	
Dryers: 8	Drips: 0	Brine/Oil: 0	Fresh Water: 0
Pumpjacks: 0	Meters: 8	Flowback: 0	Consolidation: 0
Separators: 8	Containment:	Propane: 0	Poly Vent: 0
Compressors: 0		Production: 2	

RTN Other Data

H2S Detected	☐ Yes ☒ No	ppm	Corrosion: None	Leaking: No
--------------	---	-----	-----------------	-------------



v2025.4.2

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL
PROTECTION OFFICE OF OIL AND GAS

**INSPECTION REPORT ROUTINE
INSPECTION**

**DEP USE
ONLY**

Complaint Record
No.

Inspection Record
No.
4249598

Enforcement
Record No.

Photos Attached	Additional Documents	WQS follow up	Inspection Results
☒ Yes ☐ No	☐ Yes ☒ No	☐ Yes ☐ No	NOVIO - No Violations Noted
Remarks: On 8/3/26 at 1:32 PM, I arrived at the Gaut 4IHSU well pad to conduct a Routine/Complete inspection on (129-28877). At the time of the inspection the well is open and in production. The well is shut in and currently not in production. The most recent production report for 5/31/26. No production has been submitted for 2026. The annual production report list the well as temporarily not producing. The Mechanical Integrity Assessment list an inspection date of 12/31/25. The report was submitted on 2/13/26. In the report the operator list a Primary Production Pressure of 2831 psig and a Production Annulus Open flow or Shut in Pressure of 38 no corrosion issues. The site has a total of 8 wells, 7 are currently active. All the active wells are connected to GPUs and production tanks. At this time no violations will be cited.			



v2025.4.2

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL
PROTECTION OFFICE OF OIL AND GAS**INSPECTION REPORT ROUTINE
INSPECTION****DEP USE
ONLY**Complaint Record
No.Inspection Record
No.
4249598Enforcement
Record No.

On Site Representative		DEP Representative	
 (signature)		 (signature)	
(print name)		MATTHEW THOMAS WOODS, OIL GAS INSP (print name)	
Date: 08/03/2026		Time Arrived: 01:32 PM	Time Departed: 01:38 PM

INSPECTION IMAGES



#: 1

Well tree with API number attached.



#: 2

Production tanks on site.



#: 3

Active wells on site.



#: 4

Active wells on site.

**INSPECTION REPORT ROUTINE
INSPECTION**



#: 5

Gas processing units.



#: 6

Act 9 sign